

Inspection Report

[View Project](#)

[View Inspection](#)

1 - Private - 100 Keenan Ct

Address

100 Kennan Ct
Verona WI 53593

Inspector: Rachel Clark, Civil Intern (715) 213-8054
rachel.clark@aecom.com
Inspection Date: 11/21/2023
Inspection Time: 12:16 PM
Weather Trends: Partly Cloudy
Temperature: 54 F
Last Precip. Date: 11/08/2023
Last Precip. Amount: 0.41 in
Last Precip. Source: Rain Gauge
Reason for Inspection: Routine
Comments:

Inspection Items

Name: Admin/ Site Conditions -- Photo Documentation of Site

Required: Yes

Inspected: Yes

Status: Active

Condition: Correct

Description: Photo showing current site conditions.

Comment:



Name: Control Structure -- Pipe Condition

Required: Yes

Inspected: Yes

Status: Active

Condition: Correct

Description: Check the condition of piping for damage or obstruction.

Comment:



Name: Bioinfiltration -- Standing Water

Required: Yes

Inspected: Yes

Status: Active

Condition: Correct

Description: Inspect bioinfiltration area for presence or evidence of standing water.

Comment:

Name: Bioinfiltration -- Eroded or Muddy Channel

Required: Yes

Inspected: Yes

Status: Active

Condition: Correct

Description: Inspect channels for signs of erosion, scouring or presence of excessive solids in flow.

Comment: add rip rap to concrete ramp inlets to prevent erosion and gullies forming



Name: Admin/ Site Conditions -- Trash/ Debris

Required: Yes

Inspected: Yes

Status: Active

Condition: Routine Maintenance

Description: Describe presence of trash or debris on the site requiring attention or removal.

Comment: clean up trash and vegetation debris around inlet pipe and in basin



Name: Admin/ Site Conditions -- Miscellaneous

Required: Yes

Inspected: Yes

Status: Active

Condition: Correct

Description: Wildlife Observations.
Vandalism.
Fence condition (if applicable).
Signage (If applicable).
Any other observations.

Comment: back patio cleaners and manholes in good condition



Name: Bioinfiltration -- Sediment Accumulation

Required: Yes

Inspected: Yes

Status: Active

Condition: Correct

Description: Inspect bioinfiltration area for excessive sediment accumulation or clogging.

Comment: little to no leaf debris and sediment accumulation in outlet structure



I certify under penalty of law that this document and all attachments were prepared by me or under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. To the best of my knowledge and belief, the information submitted is true, accurate and complete. I am aware that there may be penalties imposed for knowingly submitting false information.

Signature

Date